

BOAT LINE

SPEED UNDERCOAT

Two-pack polyurethane intermediate coating

CODE 72-100

DESCRIPTION AND USE

Two-pack polyurethane enamel undercoater for two-pack paint systems. Quick-drying and excellent sandability ensure a perfect superficial finish. It can be used as undercoat in epoxy or polyurethane paint systems as they require sandability and an extremely uniform surface prior to topcoat application.

APPLICATION DATA

1h DRYTO TOUCH

12h HARD DRY min 4h max 72h RECOAT TIME 5mil THEORETICAL COVERAGE 35mil PRACTICAL COVERAGE







AIRLESS Ø 0.013"-0.018" Pressure:150 atm



TECHNICAL DATA

| TECHNICAL DATA | |
|------------------------|--|
| COMPOSITION | Based on polyurethane binders and special extenders |
| SPECIFIC GRAVITY | 1.45±0.05 Kg/L |
| AVERAGE VISCOSITY | (Cone/Plate at 25℃): 3.5 Poise |
| FILM THICKNESS | Dry: 50 – Wet: 200 (μm) |
| FINENESS OF GRIND | 20 μm |
| SOLIDS BY VOLUME | 25±2% |
| V.O.C. % BY WEIGHT | 29.58 |
| FLASH POINT | >21℃ |
| MIXING RATIO BY VOLUME | BASE: 4 CATALYST: 1 |
| POT-LIFE | 6 h |
| COLOURS | White |
| PACKAGING | ml 2500 – ml 750 |
| STORAGE | Store in a cool, dry place with adequate ventilation |





PAINT SYSTEM

Epoxy system

Apply one or two coats of Speed Undercoat over the pre-existent epoxy primer. Pay attention to the recoat time of the intermediate epoxy. If recoat time exceeded, roughen the surface throughly to help adhesion. Once the product is applied, wait 8 hours and sand. Finish with Top Gloss.

Topside (new)

Fiberglass

Surface preparation: Clean and degrease the gelcoat from releasing agents used in the moulds and abrade the gel coat with fine abrasive paper.

Apply one coat of AntiPest. If necessary, fill with Finishing Filler and apply one or two coats of Speed Undercoat. The surface can be sanded after 8 hours. Finish with Top Gloss.

CONDITIONS FOR APPLICATION

Apply at a temperature between 5° C and 35° C. Do not apply when the surface temperature is below 3° C at dew point.

INSTRUCTIONS FOR USE

Shake well the two components and mix them together. Let rest for 15 minutes before use.

The product is ready to use. If necessary, thin with Thinner N° 10.

The technical data are based on a a reference temperature of 20°C unless otherwise specified and refer to the product undiluted and ready-to-use.

SAFETY PRECAUTIONS

Wear appropriate personal protective equipment; use safety equipment; use with adequate ventilation. For additional safety information, please see the package label.

This version supersedes any prior version.

Orazio Brignola S.p.A. reserves the right to update the above data, which are given for information only. If products are not used beyond our control our liability is limited to the quality of the product itself.

42 Revisione N°2 del 19/01/2009